

ARRIVAL DESCRIPTION

HECTOR TRANSITION (HEC.REEDR3): From over HEC VORTAC via HEC R-211 and PDZ R-030 to CIVET INT, then LAX R-068 to REEDR INT. Thence....

PEACH SPRINGS TRANSITION (PGS.REEDR3): From over PGS VORTAC via PGS R-229 and PDZ R-046 to RUSTT INT, then LAX R-068 to REEDR INT. Thence....

TWENTYNINE PALMS TRANSITION (TNP.REEDR3): From over TNP VORTAC via TNP R-254 to PIONE INT, then LAX R-068 to REEDR INT. Thence....

....From over REEDR INT via heading 220° for radar vector to final approach course for Runways 6 or 7.

LOST COMMUNICATIONS: Depart REEDR INT heading 220° to intercept the SLI R-251 to TANDY INT/SLI 30 DME.

SW-3, 17 DEC 2009 to 14 JAN 2010

SW-3, 17 DEC 2009 to 14 JAN 2010